


#478 - 201 Dishwasher

Completed with Issues | Andy Chang | Damage Reported

Plan: Level 2A

Created 03-04-2026



Task messages (time in PDT)

Installer IQIS	Photo 1 - GPS: 49.1927225, -122.8146641	30 Apr 08:25 AM
Installer IQIS	Photo 2 - GPS: 49.1927225, -122.8146641	30 Apr 08:25 AM
Installer IQIS	Photo 3 - GPS: 49.1927021, -122.8148229	30 Apr 08:25 AM
Installer IQIS	Ritish- Damage found on the top of the door before installation but site approved to install	30 Apr 09:30 AM
Installer IQIS	Photo 4 - GPS: 49.1926221, -122.8147879	30 Apr 09:31 AM
Installer IQIS	Ritish installed	30 Apr 09:31 AM
Installer IQIS	Photo 5 - GPS: 49.1926306, -122.8152762	30 Apr 12:37 PM
Installer IQIS	Ritish- connections done	30 Apr 12:37 PM

Photos



